

**APPENDIX A
Project Photos**

APPENDIX A- CONSTRUCTION PHOTOS SEPTEMBER 2007



Excavation of bypass channel



Placement of sandbags as a temporary dam to dewater channel.



Pumps assisted with dewatering channel.



DFG coordinated fish rescue activities (no salmonids were found).



Construction of boulder riffle.



Forming of fish screen.



Installation of pipes under the river channel.



Construction of the fish screen and grating.



Installation of fish screen cleaning brushes.



Removal of the earthen and sandbag dams.




Backfill of temporary bypass channel.



Removal of the Araujo Dam

NOVEMBER 2007



Stream bank armoring upstream from temporary bypass channel inlet (Oct/Nov 2007)



Installation of floodplain/riparian pipelines on the east side of the river November 2007.